

Id	Rfid	Codigo Barras	Numero Parte	Modelo	Lote	Descripcion	Fecha Alta	Proceso Actual Id	Estatus Actual	Total Pasadas Canteadora	Ultima Lectura	Activo
1,257	E2801190A5030063DE33180E	8414646241093	NULL	NULL	NULL	NULL	2026-07-16 04:09:03	ARMADO_PUERTAS	EN_ARMADO_PUERTAS	3	2026-07-16 08:39:36	1
1,258	E2801190A5030063DE32D3EE	3276007788518	NULL	NULL	NULL	NULL	2026-07-16 04:09:44	ARMADO_PUERTAS	EN_ARMADO_PUERTAS	2	2026-07-16 08:39:36	1
1,259	E2801190A5030063DE33181E	X000M4L1EB	NULL	NULL	NULL	NULL	2026-07-16 04:09:57	ARMADO_PUERTAS	EN_ARMADO_PUERTAS	5	2026-07-16 08:39:37	1
1,260	E2801190A5030063DE324EDE	13PD-00550-0-1	NULL	MUEBLE	NULL	NULL	2026-07-16 08:36:15	Muelle Carga	EN_MUELLE CARGA	0	2026-07-16 10:37:18	1
1,261	E28069150000600F743678B9	13PD-00550-2-3	NULL	MUEBLE	NULL	NULL	2026-07-16 08:36:38	Muelle Carga	EN_MUELLE CARGA	0	2026-07-16 10:37:23	1
1,262	E2801190A504007979DEE8FB	26PD-0320-14-15	NULL	MUEBLE	NULL	NULL	2026-07-16 08:36:48	Muelle Carga	EN_MUELLE CARGA	0	2026-07-16 10:37:18	1